June 2, 2021

?

Re: Assured : BARTOLOME JR ROSERO FABRICANTE

Policy No. : PC-RO01A01-1991970

Unit : 2018 TOYOTA HILUX 2.4L 4X2

Plate No.

Accident : 11-01-2020 Nature of Claim : Own Damage

Labor: Straighten, Align, Repaint

Parts to be Replaced:Original DiscountTIP DiscountFr Bumper0.000.00

lower grill 0.00 0.00

Total Cost of RepairPs31,000.00Less: Deductible(Ps?)

NET INSURER LIABILITY Ps 28,200.00

Thank you.

Very truly yours,

AL CAYACAP

Handling Adjuster

Note: Deductible is based on number of accidents occured.

arcus / 11:51 am / 06/02/21