

June 3, 2021

?
?

Re: Assured : PAMELA B. OFRENEO
Policy No. : CV-GA01-1167084
Unit : 2016 CHEVROLET TRAILBLAZER
Plate No. : WD0477
Accident : 04-27-2019
Nature of Claim : Own Damage

Labor: Straighten, Align, Repaint

Parts to be Replaced:	Original Discount	TIP Discount
FRONT BUMPER COVER	0.00	0.00
Total Cost of Repair	Ps 34,342.40	
Less: Deductible	<u>(Ps ?)</u>	
NET INSURER LIABILITY	Ps 34,342.40	
	=====	

Thank you.

Very truly yours,

ROMEO M. AREGLADO
Handling Adjuster

Note: Deductible is based on number of accidents occurred.